Page 1

Thursday, Septen	ıber 16, 201	0 8:58:32 AM			1 (58)(8 6)((8 1))						rugor
Revision ID:	PB67-43001	,		,	Accept -		1111 1111 1111 1111	 S	Setup Star	1 19911191 9	
	9/16/2010	Start Qty: 6.00 Req'd Qty: 6.00	۶			Cust Item I Customer:	D: 👼			1 10 3 111 0 1 0	1818 18 186 1881
Approvals:		an: MV-	Date: ſ Date:	0-9-16	Tooling: SPC (Y/N):		ate:	Į	Run Star Sto	1 (4 8 1) (4 1	
Sequence ID/ Work Center ID)	Operation Description			Set Up/ Run Hours	Tool ID	Tool # Plan	Accept Qty,	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr B67-43001	Rev	vision Nbr		,		â					
100 Bandsaw		BAND SAW Memo	7	. :	0.00 0.00	Links		_6	<u> 8</u>		
Jeaspa Bandsaw		Cut blank	s: 1.250" x 1.2	50" x 2.250" lo	ng	10/10/0/					
HAAS 1	machine #1	HAAS CNC VERTIC. Memo Machine:		544 and Dwg F	0.00 0.00 167-43001 b . f .	+ 10/10/04	e de la companya de l	6	<u>&</u>		
		Dwg Rev Folio Rev	e			, '			5 •		

Manually tap part as per Dwg B67-43001

Deburr

Dart Aerospac	e:	Ltd
---------------	----	-----

	oopao.	J = 14										
W/O:			WORK ORDER CHANGES									
DATE	STEP	PROC	CEDURE CH	IANGE	Ву	Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
								:				
Part No	•	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQA: _	Date: _					
	R	esolution:	Disposit	ion:	QA: N/C Clo	sed:	Date: _					
NCR:		W	ORK OR	DER NON-CONFORMAI	NCE (NCR)						
DATE	STEP	Description of NC		Corrective Action Section		Verificati	on Approval	Approval				
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector				
							·					

F NOTE: Date & initial all entries

Work Order ID 62110

Thursday, September 16, 2010 8:58:32 AM



Page 2

Item ID:

PB67-43001-277

Accept

Setup Start

Stop



Revision ID:

Item Name:

Contoured Male Eye

Start Date:

9/16/2010

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID:

Customer:

Reference:

An	prova	e٠
1 1	91 O 1 W	

Process Plan: _____ Date: ____ Tooling:

Set Up/

Run Hours

Date:

Start Run



Required Date: 9/30/2010

QC: ____

Date: _____ SPC (Y/N):

Date:

Tool # Plan

Code

Accept Qty

Reject Qty

Stop

Reject Insp. Number Stamp

120

Sequence ID/

Work Center ID

Quality Control

Operation Description

QC2- Inspect parts off machine FAI/FAIB

0.00

Tool ID

130

QC

Quality Control

QC8- Inspect parts - second check

Memo

Memo

Memo

0.00

0.00

140

Packaging

Packaging

Identify as per dwg & Stock Location: 0.00

0.00

(0, 10, 0H.

Dart Aerospac	e	Ltd
---------------	---	-----

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			· · · · · · · · · · · · · · · · · · ·	·		- · · · ·	<u> </u>		
Part No	•	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	A:	Date: _	
	Re	esolution:	Dispositi	on:	_ QA: N/C C	osed:		Date: _	
NCR:		V	VORK ORI	DER NON-CONFORMA	NCE (NCF	3)			
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector
					· · · · · · · · · · · · · · · · · · ·				

NOTE: Date & initial all entries

Work Order ID 62110

Thursday, September 16, 2010 8:58:32 AM



Page 3

Item ID:

PB67-43001-277

Contoured Male Eve

Accept



Setup Start



Stop



Item Name: **Start Date:**

Revision ID:

9/16/2010

Start Qty: 6.00 Rea'd Otv: 6.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Start



Required Date: 9/30/2010

QC:

Date: _____

SPC (Y/N):

Date:

Stop



Sequence ID/

Work Center ID

Operation Description

Set Up/ Run Hours 0.00

Tool ID

Tool # Plan Code

Accept Reject Qty Qty

Run

Reject Number

Insp. Stamp

150

Memo

QC21- Final Inspection - Work Order Release

0.00

Ouality Control

10/10/05 H) M- 05

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					·				1 Tod Ivigi	
			,							
						-				
								Ē		
Part No	:	PAR #:	Fault Cate	gory:	NCR: Ye	es No	DQ/	A :	Date:	
	R	esolution:	Dispositio	n:	QA: N/C	Clos	ed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	CR)				
DATE	STEP	Description of NC	Corrective Action Initial Action Desc		Section B		Verification Section C		Approval	Approval
		Section A	Chief Eng	Chief Eng		ate	Section	on C 	Chief Eng	QC Inspector
					·					
		:								
;	,									·
						:				

NOTE: Date & initial all entries

Picklist Print

Thursday, September 16, 2010 8:58:31 AM

Work Order ID: 62110

PB67-43001-277

Parent Item Name: Contoured Male Eye



Start Date: 9/16/2010

Required Date: 9/30/2010

Page 1

Start Qty: 6.00

Required Qty: 6.00

Comments:

Parent Item:

IPP A□05.07.19□New issue□KJ/JLM□

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M6061T6B1.250X01.25		Purchased	No		100	f	13.6290	0.1875	1.184211			



6061-T6 Bar 1.25 x 1.25

Location Loc Code Loc Qty MAT03 13.62895053 106259 7.06921053 110001

6.55974

1.184 om/10/10/01

Dart Aerospace Ltd

W/O:										
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		4								
					,					:
				**************************************					<i>'</i>	
,										
Part No		PAR #:	Fault Cate	gory:	NCR:	Yes N	lo DQA	۱:	_ Date:	·
	R	esolution:	Dispositio	n:	QA: N	VC Clo	sed:		Date:	
NCR:		1	WORK ORD	ER NON-CONFORMAN	NCE ((NCR)				
DATE	STEP	Description of NC		Corrective Action Section			Verific	ation	Approval	Approval
DAIL	SILP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
									:	
		·								
						•	ļ			
		,								

NOTE: Date & initial all entries


DART AEROSPACE LTD	Work Order:	62110
Description: Contouced Male Eye	Part Number:	PB67-43001-277
Inspection Dwg:BG743001-777 Rev:		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

Drawing	action in	Actual			Method of	
Dimension	Tolerance	Dimension	Accept	Reject	Inspection	Comments
1. 35	+/030	1.352	V		Dopht Gage	6A-08
RO.88	+/030	RO.880	V		Rad Gage	ref.
0.700	-+/010	0.698	✓		Vero	GA-01
0.425	+/010	0.424	~		()	, 1
100	+/支0	100	~		Angle weter	CNC-03
Ø0.313	+.006/001	Ø0.315	✓		Vein	6A-01
2.00	+/-'.030	2.000	~		11	11
0.400	+/010	0.397	~		.11	(1
0.25	+/030	0,251	~		()	<i>c</i> 1
1.00	+/~ .030	0.999	V		(1)	, ,
R U.25	+/030	RO.250	V		Rad gage	ref.
1.20	+/030	1.203	>		Vein	6A-01
R 0.13	+/030	RO.130	~		Rad gage	124.
0.75	+/030	0.752	~		Vern	GA-01
0.30	+/030	0.302	V		()	()
0.25	+/030	0.247	V		"	()
0.85	+/030	0.850	V		(1	′1
R 0.13	+/030	RO.130	✓		Rod gage	(ef.
33.00	+/- 20	33.0°	✓		Angle meter	(NC-03
					J	
			-			

Measured by: B.A.		Audited by:	Preliminary Approval:	
Date: 10 10 0	4	Date:	Date:	-

Rev	Date	Change	Revised by	Approved
E	10.04.14	Added preliminary approval	KJ	





6) IDENTIFICATION: N/A

7) WEIGHT: 0.09 lbs

DE APPR.

DATE

COPYRIGHT © 1995 BY DART AEROSPACE LTD
THIS COCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONCIDENT OF THE PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE AUTHORISE CONCIDENTIAL AND IS SUPPLIED TO MAKE CONFIDENTIAL AND CON

NTS

N/A

09.02.24

Dart Aeı	ospace	e Ltd			•	No.			è	: .	
W/O: 🐔				W	ORK ORDER	CHANGES	_				
DATE	STEP		PRO	CEDURE CH	IANGE	,	Ву	Date	Qty	Approval Chief Eng /* Prod Mgr	Approva QC Inspector
			3	æ.	·						
									ζ,		
	·;	,									**************************************
Part No		PA	AR #:	Fault Ca	tegory:	NC	R: Yes	No DQ	A :	Date:	
	R	esolution:		Disposit	ion:	Q <i>A</i>	A: N/C C	Closed:		Date: _	
NCR:			V	VORK OR	DER NON-CO	NFORMANC	E (NC	R)			
DATE		Description of	of NC	Corrective Act	tion Section B		Verifi	cation	Approval	Approval	
	STEP	Section A		Initial Action Description Chief Eng Chief Eng			Sign Date	& Section C		Chief Eng	QC Inspector
						•		·			
					<u> </u>						<u> </u>

NOTE: Date & initial all entries